

1. NUMBER: <b>PDS-00-004</b>	2. PCN: <b>PB20212</b>	<b>MSFC ENGINEERING CHANGE REQUEST (ECR)</b> (See Instructions - MSFC Form 2327-2)		3. DATE: <b>11/30/00</b>	4. PAGE  <b>1 of 1</b>
5. TO: <b>FD32/Barbara Cobb</b>		6. THRU: <b>John Ulman</b>		7. FROM: <b>Kristina Lovio-Taskov</b>	
8. TITLE OF CHANGE: <b>Revision to PDS file for Dosmap Increment 2 operations</b>					
9. RECOMMENDED PRIORITY: <input type="checkbox"/> Emergency <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> Routine			10. NEED DATE:		
11. PROGRAM(S)/PROJECT(S) AFFECTED: <b>ISS</b>			12. CONFIGURATION ITEM(S) AFFECTED BY NOMENCLATURE: <b>Increment 2 US PODF</b>		
13. RECOMMENDED EFFECTIVITY(IES): <b>Increment 2</b>			14. DOCUMENTATION AFFECTED (Specs, ICD, etc.):		
15. RELATED CHANGES (ECR, ECP, CR, etc.) BY NUMBER: <b>ECR PDS-00-001</b>			15A. INITIATING DOCUMENT NUMBER, e.g., DR, Software Trouble Report, etc.		
16. JUSTIFICATION FOR CHANGE (Include effect if not incorporated). (If necessary, continue on MSFC Form 2327-1 -Continuation Sheet) <b>Revised file is M2ULPDSN008, enclosed. Acceptance will require revision to the MGULPDSVR001, MGULPDSVP001, M2ULPDSLF001, MGULPDSM014 and the M2ULPDSFL001.</b>					
17. EFFECTS ON: <input type="checkbox"/> Hardware <input type="checkbox"/> Facility <input type="checkbox"/> Schedule (See Enclosure for impact) <input type="checkbox"/> Requirements Documentation <input type="checkbox"/> Software <input type="checkbox"/> Environment <input type="checkbox"/> Cost (Estimated cost included in Enclosure ) <input checked="" type="checkbox"/> Other (Specify): <b>US PODF</b>					
18. DESCRIPTION OF CHANGE (Include reference to enclosures). (If necessary, continue on MSFC Form 2327-1-Continuation Sheet) <b>Instruction to initialize the RAM register of the TLD Reader clock, following clock changeout, was added to the TLD READER CLOCK CHANGEOUT procedure (M2ULPDSN008, enclosed).</b>					
19. MOD KIT INFORMATION:					
Yes No				Enclosure	Paragraph
<input type="checkbox"/> <input type="checkbox"/> Previously issued modification instructions affected? (Explain)					
<input type="checkbox"/> <input type="checkbox"/> Proofing of modification instructions and kit installation required? (Explain)					
Proofing Location:					
<input type="checkbox"/> <input type="checkbox"/> Retest required? (Identify test invalidated by change)					
<input type="checkbox"/> <input type="checkbox"/> Requalification required? (Include description of test plan for requalification)					
Vehicle/Site & CI Serial No.	Change Period	Mod Kit Delivery Date	Est. M/H for Mod Kit Instl.	Out-of-Service Time	
20. SIGNATURE OF ORIGINATOR: <b>Kristina Lovio-Taskov /s/</b>		DATE: <b>11/30/00</b>	TELEPHONE NUMBER: <b>6506040450</b>	OFFICE SYMBOL: <b>LMSO</b>	
21. CONCURRENCE					
SIGNATURE	ORG.	DATE	SIGNATURE	ORG.	DATE